



Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

CHEST WIDTH

NECK

Measure around the fullest part of the neck at the base.

SIZE CHART

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Chest	34 1/2 - 38	38 1/2 -42	42 1/2 - 46	46 1/2 - 50	50 1/2 - 53	53 1/2 - 56	56 1/2 - 59	59 1/2 - 62	62 1/2 - 65
Neck	13 5/8 - 14 1/2	14 5/8 - 15 1/2	15 5/8 - 16 1/2	16 5/8 - 17 1/2	17 5/8 - 18 1/2	18 5/8 - 19 1/2	19 5/8 - 20 1/2	20 5/8 - 21 1/2	21 5/8 - 22 1/2

COLOR INFORMATION

Black	Charcoal	Grey	Light Blue	Light Grey	Light Tan	Navy	Petrol Blue	White
PMS BLACK C	PMS 7540C	PMS 409C	PMS 7451C	PMS 422C	PMS 7536C	PMS 532C	PMS 2135C	